

**Staff Responses to Council Questions  
August 6, 2019**

**7. First Reading, A. MOT 2019-8270 A motion awarding \$924,799.30 to A Lamp Concrete Contractors, Inc. of Schaumburg, Illinois for the Indianapolis Avenue/Cross Street/Drendel Road drainage sidewalk improvements**

*What is a “Unit” and how many trees are we planning on removing for this project and of what caliber?*

The unit of tree removal in the contract describes the total inch-diameter of trees to be removed. Tree removal is measured by the addition of the diameter of all trees to be removed. The diameter of a tree is measured about four feet from the ground. The contract includes a quantity of 175 units (inch-diameter) of tree removal. After the contract was released for bid, staff did further site investigations and estimates this number could be reduced to between 100 and 120 units. Like the other pay items in the contract, the contractor will only be paid for work performed.

**Indianapolis, Drendel to Cross**

|   |  |
|---|--|
| <b>Number of Trees Removed</b>              | Three trees; 12”, 21” and 21” diameters                    |
| <b>Will Removed Trees be Replaced?</b>      | Yes  |
| <b>Reason for Tree Removal</b>              | Trees are in conflict with new sidewalk and drainage ditch |
| <b>Site Design to Mitigate Tree Removal</b> | Road design elevated and shifted south to save six trees   |

**Cross Street S-Curve**

|   |  |
|---|--|
| <b>Number of Trees Removed</b>              | One tree; 13” diameter   |
| <b>Will Removed Tree be Replaced?</b>       | Yes  |
| <b>Reason for Tree Removal</b>              | Tree is in conflict with new sidewalk; due to site conditions the tree cannot be saved |
| <b>Site Design to Mitigate Tree Removal</b> | Not possible because the road has a very narrow right-of-way                           |

**Cross, Ogden to S-Curve**

|   |   |
|---|---|
| <b>Number of Trees Removed</b>              | Four trees; 4”, 5”, 6” and 30” diameters                                    |
| <b>Will Removed Trees be Replaced?</b>      | Yes   |
| <b>Reason for Tree Removal</b>              | Trees are in conflict with new sidewalk and drainage ditch                  |
| <b>Site Design to Mitigate Tree Removal</b> | Site design includes meandering sidewalk to save approximately eleven trees |

**9. Manager’s Report, C. Information: 2019-2021 Long Range Plan - Committee Room**

*Please provide some current demographic and economic information about the Village (population, age, income, housing etc.)*

The data in the table below is provided by the [United States Census Bureau American Fact Finder](#), and was most recently updated with the 2013-2017 American Community Survey 5-year estimates. More information regarding this data can be found by clicking the link to the American Fact Finder.

| <b>DEMOGRAPHIC INFORMATION</b>       |           |
|--------------------------------------|-----------|
| Total Population                     | 49,649    |
| Median Age                           | 43.1      |
| Male Population                      | 48.8%     |
| Female Population                    | 51.2%     |
| White or Caucasian Population        | 89.5%     |
| Black or African American Population | 3.5%      |
| Asian Population                     | 7.1%      |
| Other Race Population                | 1.3%      |
| <b>ECONOMIC INFORMATION</b>          |           |
| Median Household Income              | \$85,546  |
| Median Family Income                 | \$115,755 |
| Individuals Below Poverty Level      | 5.4%      |
| Unemployment Rate                    | 5.1%      |
| <b>HOUSING INFORMATION</b>           |           |
| Total Housing Units                  | 21,130    |
| Vacant Housing Units                 | 5.1%      |
| Median Value of House                | \$340,200 |

**Attachments**

No rEmarks this week